

**Bid No. 2019-079, Annual Contract for Automotive and Light Truck
Transmission Repair**

			2J's Automotive Saginaw, TX	
			HUB - No	COOP - Yes
Item No.	Description	Est. Qty. (EA)	Unit Price	Extended Price
Section I: REPAIR TRANSMISSION				
1.	Ford Crown Victoria 4R70W	0-10	85.00/hr+parts	N/A
2.	Ford Crown Victoria 4R75W	0-10	85.00/hr+parts	N/A
3.	Ford Explorer 6F50	0-10	85.00/hr+parts	N/A
4.	Ford Explorer 6F55	0-10	85.00/hr+parts	N/A
5.	Ford Taurus 6F50	0-10	85.00/hr+parts	N/A
6.	Ford Taurus 6F55	0-10	85.00/hr+parts	N/A
7.	Chevrolet Tahoe 6L80E	0-10	85.00/hr+parts	N/A
Section II: REBUILD TRANSMISSION				
8.	Ford Crown Victoria 4R70W	0-10	\$2,350.00	\$23,500.00
9.	Ford Crown Victoria 4R75W	0-10	\$2,350.00	\$23,500.00
10.	Ford Explorer 6F50	0-10	\$3,800.00	\$38,000.00
11.	Ford Explorer 6F55	0-10	\$4,000.00	\$40,000.00
12.	Ford Taurus 6F50	0-10	\$3,800.00	\$38,000.00
13.	Ford Taurus 6F55	0-10	\$4,000.00	\$40,000.00
14.	Chevrolet Tahoe 6L80E	0-10	\$4,050.00	\$40,500.00

**Bid No. 2019-079, Annual Contract for Automotive and Light Truck
Transmission Repair**

			2J's Automotive Saginaw, TX	
			HUB - No	COOP - Yes
Item No.	Description	Est. Qty. (EA)	Unit Price	Extended Price
Section III: REMANUFACTURED TRANSMISSION				
15.	Ford Crown Victoria 4R70W	0-10	\$3,570.00	\$35,700.00
16.	Ford Crown Victoria 4R75W	0-10	\$3,570.00	\$35,700.00
17.	Ford Explorer 6F50	0-10	\$5,527.00	\$55,270.00
18.	Ford Explorer 6F55	0-10	\$6,400.00	\$64,000.00
19.	Ford Taurus 6F50	0-10	\$5,527.00	\$55,270.00
20.	Ford Taurus 6F55	0-10	\$6,400.00	\$64,000.00
21.	Chevrolet Tahoe 6L80E	0-10	\$4,730.00	\$47,300.00
Section IV: TEARDOWN TRANSMISSION				
22.	Ford Crown Victoria 4R70W	0-10	\$510.00	\$5,100.00
23.	Ford Crown Victoria 4R75W	0-10	\$510.00	\$5,100.00
24.	Ford Explorer 6F50	0-10	\$680.00	\$6,800.00
25.	Ford Explorer 6F55	0-10	\$680.00	\$6,800.00
26.	Ford Taurus 6F50	0-10	\$680.00	\$6,800.00
27.	Ford Taurus 6F55	0-10	\$680.00	\$6,800.00
28.	Chevrolet Tahoe 6L80E	0-10	\$510.00	\$5,100.00
Section V: CHARGES FOR NON-SPECIFIED VEHICLES				
29.	Hourly Labor Rate	N/A	\$85.00	N/A
30.	Mark-up Percentage for Parts	N/A	N/A	50%

Sam Pack's Five Star Ford was deemed non-responsive due to failure to submit Addendum 1 as required.